State	Measuremen t Cateαories ID	RTCS	State ID	NCWM Nadir Cal. Window	APSM Aperture Stop	NDFM ND Filter	WLS White Light Source Lamp	SLS Spectral Line Source Lamp
Nadir	1	STT_01	1 to 7; 9 to 15	Closed	Large	Out	Off	Off
Limb	2	STT_01	28 to 37; 40 to 41	Closed	Large	Out	Off	Off
Nadir_pointing	3	STT_01	23 to 25; 42 to 45	Closed	Large	Out	Off	Off
SO&C_Scanning	4	STT_02	47;49;50	Closed	Small	ln	Off	Off
SO&C Pointing	5	STT_02	51	Closed	Small	In	Off	Off
MO&C_Pointing	6	STT_01	56; 57	Closed	Large	Out	Off	Off
Moon_Scanning	7	STT_01	54	Closed	Large	Out	Off	Off
Sun_ESM_Diffusor_Calibration (ND OUT)	8	STT_09	52	Closed	Large	Out	Off	Off
Sub-solar_Calibration	9	STT_03	53;58;60	Open	Small	ln	Off	Off
Spectral_Lamp_Calibration	10	STT_04	59;69	Closed	Large	Out	Off	On
White_Lamp_Calibration (ND IN)	11	STT_10	61	Closed	Large	ln	On	Off
Dark_Current_Calibration	12	STT_01	8;26;46;63;67	Closed	Large	Out	Off	Off
Sun Nadir/Elevation_Mirror_Calibration	13	STT_02	64;66;68	Closed	Small	ln	Off	Off
Moon Nadir/Elevation_Mirror_Calibration	14	STT_01	not used	Closed	Large	Out	Off	Off
ADC_Calibration	15	STT_07	65	Closed	Large	Out	Off	Off
Sun_ESM_Diffusor_Calibration (ND IN)	16	STT_06	62	Closed	Large	ln	Off	Off
Nadir_Eclipse_Pointing	17	STT_01	not used	Closed	Large	Out	Off	Off
Nadir_Eclipse_Scanning	18	STT_01	not used	Closed	Large	Out	Off	Off
White_Lamp_Calibration (ND OUT)	19	STT_05	70	Closed	Large	Out	On	Off
Dark_Current_Calibration_HM	20	STT_09	39	Closed	Large	Out	Off	Off
NDF Monitoring (ND OUT)	21	STT_05	16	Closed	Large	Out	On	Off
NDF Monitoring (ND IN)	22	STT_10	48	Closed	Large	ln	On	Off
Sun_ASM_Diffuser	23	STT_09	17 to 21	Closed	Large	Out	Off	Off
Nadir_Pointing_Left	24	STT_01	38	Closed	Large	Out	Off	Off
Sun_ASM_Diffuser_Atmosphere	25	STT_09	22	Closed	Large	Out	Off	Off
Limb_Mesosphere	26	STT_01	27	Closed	Large	Out	Off	Off
Limb_Mesosphere_Thermosphere	27	STT_01	55	Closed	Large	Out	Off	Off